

Body and Fender Repairing — Painting — Wrecks Rebuilt
234 MARKET AVE., MOUNT JOY, PA 17552 PHONE 653-5828

OWNER <i>Warren Greenawalt</i>		PHONE		DATE <i>10/29/84</i>	
ADDRESS <i>RD#1 Mt Ly Pa.</i>		CAR LOCATED AT			
YEAR <i>83</i>	MAKE <i>Pontiac</i>	MODEL <i>2000</i>	LICENSE NO.	SPEEDOMETER	MOTOR NO.
INSURANCE CARRIER		ADJUSTER		PHONE	SERIAL NO.

DESCRIPTION OF OPERATIONS		PAIN T	PARTS	LABOR
	Straight right rear 1/4 panel			7.0
	side moldy Rear (abbr.)		16.25	.2
	refinish damage area & metal's	32.00		2.8
	stone guard paint lower 1/4 panel	5.00		.5
TOTAL		32.00	16.25	10.5
		TOTAL LABOR 199.50		
		TOTAL PARTS 16.25		
		TOTAL PAINT 37.00		
		TOWING		
		TAX 15.17		
		TOTAL OF ESTIMATE 267.92		

The above is an estimate, based on our inspection, and does not cover additional parts or labor which may be required after the work has been opened up. Occasionally, after the work has started, worn, broken or damaged parts are discovered which are not evident on first inspection. Quotations on parts and labor are current and subject to change.

ESTIMATE MADE BY _____

AUTHORIZATION FOR REPAIR – You are hereby authorized to make the above specified repairs to the car described herein.

By Owner
or Agent

Date _____